



# Transport Canada

www.tc.gc.ca

[Français](#) | [Home](#) | [Contact Us](#) | [Help](#) | [Search](#) | [canada.gc.ca](#)

[Home](#) > [Transport Canada](#) > [Road Safety](#) > [Vehicle Recalls and Defects](#) > [Road Safety Recalls Database](#) > [Search Result](#) > Results

## Main Menu

Road Safety's Main Menu

Vehicle Recalls and Defects

## VRDB v2.2.2

New Search

Modify Search

Return to Search Result Page

## Browse By Mode

Air Transportation

Marine Transportation

Rail Transportation

Road Transportation

## Road Safety Recalls Database

[Print this Page](#)

### Transport Canada Recall # 2012253

**Recall Date** 2012/08/01

**Notification Type** Safety Mfr

**System** Suspension

**Manufacturer Recall Number**

**Units Affected**  100,100

**Category** SUV

#### Recall Details

On some vehicles, if the rear wheel alignment toe adjustment locking nuts are improperly tightened when an alignment is performed in the field, backlash may develop in the threaded portion of the suspension arm (shaft and turnbuckle), followed by the formation of rust. If this occurs, threads may wear, causing the arm to separate which could result in loss of vehicle control. Correction: Dealers will inspect the arms and verify the tightening torque of the lock nuts, or replace the arms, as necessary.

Make	Model	Model Year(s) Affected
LEXUS	HS 250H	2010
TOYOTA	RAV4	2006 2007 2008 2009 2010 2011